# **Policy Newsletter** April 2024

Rosemary Roberts



Bringing energy to your door



Stay connected...











www.enwl.co.uk

### Policy Updates – Major Policy Updates



Ref	Issue	Title	Suggested Audience	Policy Dissemination Method
CP430 Pt1 OHLT 874	Contents of Manual – I12 Section 2 OHL Techniques – I10 OHL Technique 874 – I1	Linesmen's Manual – Wood Pole and Mural Wiring	Linesmen, Design/Delivery Engineers & Managers and the Academy	Stand-down
EPD282	10	Distribution System Design – HV Network	All HV Planners and Designers	Briefing Slides

### Policy Updates – Minor Policy Updates



Ref	Issue	Title	Suggested Audience	Policy Dissemination Method
CP614	42	Authorisation	All operational staff & managers.	Team Brief

# **Major Policy Updates**





#### CP430 Part 1: Linesmen's Manual – Wood Pole and Mural Wiring 🚓





New OHL Technique 874 covers removing a small sample of oil from a PMT to perform a Clor-N-Oil 50 test which will give instant indication if there are unacceptable levels of PCBs (Polychlorinated biphenyls).



If a PMT is found to contain a level of PCBs above 50ppm, (i.e., it fails the Clor-N-Oil 50 test), then it is removed from service or if the oil passes the test the PMT can be put back in service.



### EPD282 - Distribution System Design – HV Network





Clarification that interconnected tees are not permitted in the first leg of a circuit.



Previously interconnected tees have been permitted but this change recognises the presence of a breech joint in the first leg of a circuit increases the risk of a fault affecting the whole circuit.



Threshold for reinforcement intervention increased from 95% to 100%. Clarification on use of ratings.



There have been other minor updates to the document not marked

# **Minor Policy Updates**





#### Policy Updates - Minor Policy Updates



#### **CP614 – Authorisation**

- Code 183 Requirement to hold code 195 in addition if issue of safety documents is required
- Code 364 Remove the requirement to hold LV authorisation.
- Must hold code 347 for a minimum of 6 months.
- Code 110 Clarified to demonstrate including receipt of LoA for Safety Standby only
- Code 149 Allows for Telecom staff already holding code 106 and completing EO1170 to gain the code without interview.
- Code 217 Qualifications and on job training amended.
- Code 218 Qualifications and on job training amended.
- Code 344 Formal and on job training modified.
- Code 347 On job training clariid.
- Code 503, 504, 505 Clarified that these codes are for all work but in order to issue safety documents code 195 is also required.